



FA100–Inim Cloud Connection Prerequisites and Access via App/Software

FA100 Device

- Install the optional connectivity module FA100LAN or FA100WiFi
- Update the device firmware to release 1.00.02.00 using the FA100 Updater release 1.00.04.00, available on Service Previdia

Software

- Update FA Studio to version 1.3.0.0, available on the website or via live update

App

- Update the app to version 2.6, available on Google Play and the App Store

Changelog



Firmware FA100

- Added Inim Cloud support
- Service mode / detector bypassing: added “activated through other means” display and bug fixing; added access for the User as well as the Installer
- Added time zone programming from the menu
- Added save prompt when exiting settings screens
- Minor bug fixes and improvements, especially to Ethernet and WiFi communication



Software FA Studio

- **Add:**
 - Inim Cloud device programming
 - Device configuration management for connection to Inim Cloud
 - Updated solutions database to support cloud features
 - Data log event (Cloud connection fault)
- **Optimization:**
 - Improved performance of chart visualization of detector logger